

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 12193

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080077-9

RECEIVED FROM

Plant #9

DATE REC'D. 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.
	322	000000	005	0	10					
DRAWING NO. AND DESCRIPTION										
1	731983 Pin T.C. 11					QUANTITY ACCEPTED 1		REJECTED		REMARKS In Store
	IPC 7684									

RECEIVED BY *Barcellos*
HMC-1009

INSPECTED BY *JPE*

DATE 5-16-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 12195

RECEIVED FROM

Plant #

DATE REC'D. 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.
	322	000000	026	0	10					
DRAWING NO. AND DESCRIPTION										
15	737118 Washer Retainer Pivot					QUANTITY ACCEPTED 15		REJECTED		REMARKS In Store
	IPC 7682									

RECEIVED BY *Barcellos*
HMC-1009

INSPECTED BY *JPE*

DATE 5-16-57

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080077-9